

01-04-2011 to 31-03-2012

Escalator No.	Cause	Times	Sub-total
1E 中環街市地下 至 中環街市一 樓	Adjusted the braking system	1	15
	Adjusted the handrail	1	
	Checked the safety devices	1	
	Repaired the braking system	8	
	Repaired the lighting cover	1	
	Repaired the synchronization switch	1	
	Replaced the damaged auxiliary rod	1	
	Replaced the main brake	1	
2E 中環街市地下 至 中環街市一 樓	Adjusted safety switch for step	1	28
	Adjusted the handrail	1	
	Adjusted the step	1	
	Repaired the control circuit	4	
	Replaced the damaged handrail	10	
	Replaced the damaged step & comb	8	
	Reset the handrail safety device	1	
	Abnormal noise was found	2	
5T 皇后大道中天橋 至 威靈頓街天 橋	"Emergency Stop Button" had pressed by passenger	20	42
	Adjusted the braking system and repaired the control circuit	1	
	Adjusted the handrail	6	
	Checked the escalator step rail	1	
	Checked the safety devices	1	
	Repaired motor chain	3	
	Repaired the control circuit	1	
	Repaired the damaged handrail	1	
	Replaced the damaged handrail chain	2	
	Replaced the damaged step	1	
	Reset the safety device	1	
	Reset the safety device and checked the control circuit	1	
Abnormal noise was found	3		
6T	"Emergency Stop Button" had pressed by passenger	8	
	Adjusted the handrail	6	
	Checked the control circuit	1	
	Repaired the braking system	3	
	Repaired the control circuit	5	
	Repaired the control circuit and tested the brakes	2	
	Repaired the damaged handrail	9	
	Repaired the motor	7	

威靈頓街天橋 至 擺花街天橋	Repaired the step rail	1	64
	Repaired the track of the escalator	1	
	Replaced the damaged contactor	2	
	Replaced the damaged handrail	5	
	Replaced the damaged motor bearing	2	
	Replaced the damaged step	1	
	Replaced the damaged step & comb	7	
	Abnormal noise was found	3	
	Abnormal smell was found	1	
7T 擺花街天橋 至 荷李活道天橋	"Emergency Stop Button" had pressed by passenger	7	20
	Adjusted the handrail	6	
	Checked control circuit	1	
	Repaired the damaged handrail	3	
	Replaced the damaged handrail	2	
	Abnormal noise was found	1	
8E 荷李活道天橋 至 荷李活道	"Emergency Stop Button" had pressed by passenger	2	4
	Checked the safety devices	2	
9E 荷李活道天橋 至 荷李活道	"Emergency Stop Button" had pressed by passenger	3	13
	Adjusted the handrail	1	
	Checked control circuit	2	
	Repaired the control circuit	1	
	Replaced the damaged handrail and repaired the damaged handrail wheel	2	
	Replaced the damaged step	2	
	Reset the safety device	2	
10E 荷李活道 至 士 丹頓街	Adjusted the step	1	5
	Repaired the control circuit	1	
	Replaced the damaged comb	2	
	Replaced the damaged step roller	1	
11E 荷李活道 至 士 丹頓街	Checked the control circuit of energy saving lamp	1	5
	Re-fixed the side board	1	
	Repaired the control circuit	1	
	Repaired the landing floor plate	1	
	Replaced the step roller	1	
12E 士丹頓街 至 伊 利近街	"Emergency Stop Button" had pressed by passenger	2	22
	Adjusted the handrail	4	
	Checked control circuit	1	
	Repaired the PCB Board	1	
	Replaced the damaged handrail and repaired the damaged handrail wheel	1	

	Replaced the damaged step	11	
	Replaced the fuse	1	
	Replaced the step roller	1	
13E 士丹頓街至伊 利近街	"Emergency Stop Button" had pressed by passenger	1	28
	Adjusted the handrail	4	
	Checked control circuit	1	
	Checked the emergency brake and main brake system	1	
	Repaired the control circuit	10	
	Repaired the motor	6	
	Replaced the step wheel	2	
	Reset the safety device	2	
	Abnormal noise was found & adjusted the handrail	1	
14E 伊利近街至堅 道	Adjusted the handrail	10	36
	Checked the comb	1	
	Checked the safety devices	1	
	Repaired the control circuit	1	
	Repaired the damaged handrail	4	
	Replaced the damaged comb	1	
	Replaced the damaged handrail	2	
	Replaced the damaged step	2	
	Replaced the damaged step & comb	2	
	Replaced the damaged step roller and checked the control circuit	1	
	Reset the safety device	5	
	Abnormal noise was found	4	
	The interruption/failure of the electricity supply.	2	
15E 堅道至堅道天 橋	"Emergency Stop Button" had pressed by passenger	1	15
	Adjusted the handrail	3	
	Checked the emergency brake and main brake system	1	
	Repaired the damaged handrail	2	
	Replaced the bearing of the handrail drive wheel	2	
	Replaced the damaged handrail	1	
	The interruption/failure of the electricity supply.	5	
16E 堅道至摩囉廟 街	Adjusted the handrail	1	5
	Re-fixed the skirt brush	1	
	Abnormal noise was found	1	
	The interruption/failure of the electricity supply.	2	
	"Emergency Stop Button" had pressed by passenger	1	
	Adjusted the comb	1	
	Adjusted the handrail	2	

17E 堅道至摩囉廟街	Adjusted the step	1	13
	Re-fixed the side board	1	
	Repaired the control circuit	2	
	Reset the safety device	2	
	Abnormal noise was found	1	
	The interruption/failure of the electricity supply.	2	
18E 堅道至摩囉廟街	"Emergency Stop Button" had pressed by passenger	3	20
	Adjusted the handrail	1	
	Repaired the control circuit	7	
	Replaced the damaged step chain wheel	1	
	Replaced the step wheel	1	
	Reset the safety device	2	
	Abnormal noise was found	2	
	The interruption/failure of the electricity supply.	3	
19E 摩囉廟街至摩囉廟交加街天橋	"Emergency Stop Button" had pressed by passenger	3	22
	Adjusted the handrail	2	
	Checked control circuit	2	
	Checked the safety devices	3	
	Re-fixed the landing cover	1	
	Repaired the control circuit	1	
	Replaced the damaged handrail	2	
	Replaced the damaged step & comb	1	
	Replaced the step chain	1	
	Abnormal noise was found	6	
20E 摩囉廟交加街天橋至羅便臣道	"Emergency Stop Button" had pressed by passenger	1	9
	Adjusted the handrail	2	
	Adjusted the step rails and replaced damaged comb	1	
	Repaired the control circuit	1	
	Replaced the damaged handrail	1	
	Replaced the damaged step chain wheel	1	
	Replaced the damaged step chain wheel & comb	1	
	Abnormal noise was found	1	
21E 羅便臣道至羅便臣道天橋	Adjusted the handrail	6	39
	Checked control circuit	1	
	Checked the emergency brake and main brake system	1	
	Checked the safety devices	1	
	Repaired the braking system	3	
	Repaired the control circuit	2	
	Repaired the damaged handrail	3	

	Replaced the damaged motor bearing	3	
	Replaced the damaged relay	1	
	Replaced the damaged step chain roller	3	
	Reset the safety device	1	
	Abnormal noise was found	14	
22E 羅便臣道至干德道	Adjusted the handrail	3	12
	Re-fixed the landing cover	1	
	Re-fixed the side board	1	
	Repaired the control circuit	1	
	Repaired the damaged handrail	1	
	Repaired the PLC	1	
	Reset the safety device	4	
23E 羅便臣道至干德道	Checked control circuit	1	10
	Checked the braking system	1	
	Repaired the control circuit	2	
	Repaired the damaged handrail wheel	3	
	Repaired the PLC	1	
	Replaced the fuse	1	
	Abnormal noise was found	1	
Total		427	

這是初步紀錄，並已於工作小組會議中提交。由於收到議員多方面的意見，本署現正整理及更新資料。