

致： 中西區區議會
 地區設施管理委員會秘書
 沈施恩小姐
 (傳真號碼：2542 2696/ 3691 8024)

中西區區議會轄下地區設施管理委員會
地區小型工程計劃建議書
 (供議員填寫)

1. 提交建議的議員*：陳浩濂議員
2. 工程名稱：舊山頂道至克頓道的行山徑優化工程
3. 工程目的（請指出現有問題，以及建議工程的效益，例如美化景觀、加強公共衛生等）：
此行山路線廣受行山者喜愛，可惜路面凹凸不平，沒有完善的行山措施，對行山人士構成危險。優化行山徑能夠保障行山人士的安全，讓他們好好享受行山的樂趣。
4. 工程受惠對象：
 () 區內所有居民 () 傷殘人士
 () 老人 () 兒童及家長
 () 青少年 () 其他： 各區行山人士
5. 預期受惠人數： 區內區外行山人士
6. 工程造价粗略估計（可選擇不填寫）： _____
7. 工程大綱（請詳述有關工程細節、項目規格、如何與現有設施銜接等）：
優化路面情況，改善路面凹凸不平

8. 工程地點（請夾附地圖明確標示工程地點）：舊山頂道至克頓道 (參照地圖)

9. 工程時間表粗略估計（可選擇不填寫）： _____
10. 其他與工程有關的資料（例如早前曾否作出申請、有否類似例子以供參照等）： _____

簽名： _____

姓名： 陳浩濂

日期： 2016年10月6日

Path from Old Peak Road to Hatton Road - only the portion from Old Peak Road to Po Shan Road is currently passable.



There is a wonderful path which used to run from the bottom of the pedestrian section of Old Peak Road (Point A) to Hatton Path (Point D) via the service reservoirs (Point C).

Sadly neglect of the path and slope stabilisation work now makes it very difficult to get from Point B to Point C. Instead one walks from Old Peak Road to Point B and then on to Po Shan Road.

There is a vacant building plot at Point B. A worry is the construction on this site may make it difficult to get from the path to Po Shan Road.

Requests:

1. That the Government repairs the path between Points A and B. Further that it ensures that any development at Point B is done in a way which provides easy access from the path to Po Shan Road.
2. That the Government repairs the path between Points B and D

Path from Old Peak Road to Hatton Road - only the portion from Old Peak Road to Po Shan Road is currently passable.

